










18550-154

1 / 5






Møtrikker (D+E) strammes til når hele bænken er samlet.

Erst nach der kompletten Montage alle Schraubenmuttern (D+E) fest anziehen.

The nuts (D+E) are tightened when the hole set have been assembled.

Muttrarna (D+E) skruvas åtdragna när hela bänken är monterad.


Les écrous (D+E) sont serrés lors du montage des planches.





A		5x50 TX	x4
B		M8x80	x20
C		M8	x20
D		M8	x16
E		M8 lock	x4


1

2 / 5




Monteres - men fastskrues ikke endnu.
 Montiert - aber noch nicht festgeschraubt.
 Mounted - but not yet tightened.
 Monterad - men ännu inte fastskruvad
 Installé - mais pas encore vissé.





B  **M8x80** **x4**




2




Monteres - men fastskrues ikke endnu.
 Montiert - aber noch nicht festgeschraubt.
 Mounted - but not yet tightened.
 Monterad - men ännu inte fastskruvad
 Installé - mais pas encore vissé.





B  **M8x80** **x4**




C		M8	x8
D		M8	x8




Monteres - men fastskrues ikke endnu.
 Montiert - aber noch nicht festgeschraubt.
 Mounted - but not yet tightened.
 Monterad - men ännu inte fastskruvad
 Installé - mais pas encore vissé.



B		M8x80	x4
----------	---	--------------	-----------

5



Monteres - men fastskrues ikke endnu.



4 / 5

Montiert - aber noch nicht festgeschraubt.


Mounted - but not yet tightened.

Monterad - men ännu inte fastskruvad

Installé - mais pas encore vissé.






B




M8x80

x4

6



13mm



C



M8

x8

D






M8


x8

7





5 / 5



B		M8x80	x4
C		M8	x4
E		M8 lock	x4



8



A		5x50 TX	x4
----------	---	----------------	-----------